


# Valley Crossing Over Time




07/01/42 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4024 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance

This photo was in the Geology and Geomorphology section of the North Coast Watershed Assessment - Gualala (Klamt - 2003). The annotation was by Michael Fuller, CEG. "Upper photo shows channel in 1942 meandering north into toe of landslide."



09/22/52 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4012 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is dry but seems to cross over to the right bank where the new bridge is now.

---



09/15/56 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4014 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is in the center of the channel.

---



05/04/59 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4022 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is in the center of the channel.

---



09/15/71 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4013 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork seems to cross over to the right bank where the new bridge is now.

---



06/26/84      0 ' Up   Wheatfield      Dir 0      Cr Station 0      LWD Site      0  
12:00 PM   Photo 4019   Road# 40      Mi. 1.6      Map Pt. 2450   THP Maintenance  
The South Fork crosses over to the right bank under the new bridge.

---



08/16/88      0 ' Up   Wheatfield      Dir 0      Cr Station 0      LWD Site      0  
12:00 PM   Photo 4015   Road# 40      Mi. 1.6      Map Pt. 2450   THP Maintenance  
The South Fork crosses over to the right bank under the new bridge. It seems dry.

---



06/26/93 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4018 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is in the center of the channel.

---



06/08/94 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4021 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is in the center of the channel.

---



07/01/96 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4017 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is on the right side but not up against the bank.

---



07/17/98 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 4016 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance  
The South Fork is on the right bank.

---



04/22/02      0 ' Up   Wheatfield      Dir 0      Cr Station 0      LWD Site      0  
12:00 PM   Photo 4023   Road# 40      Mi. 1.6      Map Pt. 2450   THP Maintenance  
The South Fork is on the right bank.

---



06/16/04      0 ' Up   Wheatfield      Dir 0      Cr Station 0      LWD Site      0  
12:00 PM   Photo 4020   Road# 40      Mi. 1.6      Map Pt. 2450   THP Maintenance  
The South Fork is on the right bank.

---



07/15/10 0 ' Up Wheatfield Dir 0 Cr Station 0 LWD Site 0  
12:00 PM Photo 5908 Road# 40 Mi. 1.6 Map Pt. 2450 THP Maintenance

---