

GUALALA RIVER WATERSHED RESTORATION AND MONITORING

Monitoring Reach
Number of Visits Label

- 0 visits
- at least 1 visit

Road Status

- Abandoned
- Decommissioned
- Storm-Proofed
- Upgraded

- ◆ Water Temperature Monitoring
- Large Wood Placement (white dot on stream channel)
- Super Planning Watershed
- ⋯ PWS Boundary

Scale 1:48000

